

Inspection Photos

11/14/2025

Operator: Chevron USA Inc #16700

Location ID: 397075

Inspection Doc: 719200461

Rio Blanco County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: Chevron USA Inc #16700

Location ID: 397075



Photo 1: Photos showing an overview of the location looking north and south, respectively. Gravel and compaction is evident throughout the location. The location has not been reclaimed pursuant to 1004 reclamation requirements.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: Chevron USA Inc #16700

Location ID: 397075



Photo 2: Photos showing an overview of the location looking east and west, respectively. Gravel and compaction is evident throughout the location. The location has not been reclaimed pursuant to 1004 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Chevron USA Inc #16700

Location ID: 397075



Photo 3: Photo showing the plugged and abandoned well marker at the location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Chevron USA Inc #16700

Location ID: 397075



Photo 4: Photos showing an overview of the southern access road leading to the location. The access road does not appear to be reclaimed per 1004 reclamation requirements; gravel and compaction is evident.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Chevron USA Inc #16700

Location ID: 397075



Photo 5: An unknown grey-colored waste material, likely concrete, is present at the southeast end of the location and requires removal pursuant to Rule 906.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Chevron USA Inc #16700

Location ID: 397075



Photo 6: Photos showing an overview of the location. An intermittent stream, which was flowing at the time of inspection, lies directly west of the location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources