

# Final Reclamation Inspection

October 31, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 328152

Inspection Document #: 718801006

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: HSR-BEALL #16-17  
Location ID: 328152



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place. However, vegetation has not established to Rule 1004 standards and the location appears to be within fallow cropland.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos  
Location Name: HSR-BEALL #16-17  
Location ID: 328152




**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos  
Location Name: HSR-BEALL #16-17  
Location ID: 328152



**Photo 5.** Photo taken of ground cover at the well location. Photo illustrates weedy annual vegetation including Kochia (*Bassia scoparia*).



**Photo 6.** Photo taken of the access road the well location, facing east. Photo illustrates that the access road does not meet Rule 1004 standards as gravel, bare ground, and weedy annual vegetation were observed across the road.

Inspection Photos  
Location Name: HSR-BEALL #16-17  
Location ID: 328152



**Photo 7.** Photo taken of the reference area to the location, north of the location, facing northwest. Photo illustrates weedy annual vegetation and appears to be fallow cropland.

