

Final Reclamation Inspection

October 31, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 328152

Inspection Document #: 718801008

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HSR-BEALL #16-17
Location ID: 328152



Photo 1. Google Earth Aerial Imagery from October 6, 2014 depicting the abandoned multi-well location prior to location abandonment.

Inspection Photos
Location Name: HSR-BEALL #16-17
Location ID: 328152



Photo 2. Google Earth Aerial Imagery from February 4, 2025 depicting the abandoned multi-well location after location abandonment.



Inspection Photos
Location Name: HSR-BEALL #16-17
Location ID: 328152



Photo 3. Photo taken from the abandoned multi-well location, facing north. Photo illustrates that there is no evidence of oil and gas disturbance at the abandoned portion of this location and based on records only one well was drilled (PA Well API# 123-15617).



Photo 4. Photo taken of the abandoned multi-well location, facing east. See comments under Photo 3.



Inspection Photos
Location Name: HSR-BEALL #16-17
Location ID: 328152



Photo 5. Photo taken of the abandoned multi-well location, facing south. See comments under Photo 3.



Photo 6. Photo taken of the abandoned multi-well location, facing west. See comments under Photo 3.

