

Final Reclamation Inspection

October 31, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 336129

Inspection Document #: 718801014

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: HSR FEDERAL-63N66W/36SENE

Location ID: 336129



Photo 1. Photo taken of the multi-well location, facing north. Photo illustrates that final reclamation activities have taken place. However, vegetation has not established to Rule 1004 standards and weedy annual vegetation including cheatgrass (*Bromus tectorum*) and russian thistle (*Salsola tragus*) was observed across the location.



Photo 2. Photo taken of the multi-well location, facing east. See comments under Photo 1.



Inspection Photos

Location Name: HSR FEDERAL-63N66W/36SENE

Location ID: 336129



Photo 3. Photo taken of the multi-well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the multi-well location, facing west. See comments under Photo 1.



Inspection Photos

Location Name: HSR FEDERAL-63N66W/36SENE

Location ID: 336129



Photo 5. Photo taken of ground cover at the location. Photo illustrates weedy annual vegetation including russian thistle (*Salsola tragus*) and cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.



Photo 6. Photo taken of the access road to the multi-well location, facing northwest. Photo illustrates that the access road does not meet Rule 1004 standards.



Inspection Photos

Location Name: HSR FEDERAL-63N66W/36SENE

Location ID: 336129



Photo 7. Photo taken of the reference area to the location, east of the location, facing east. Photo illustrates sand sagebrush, perennial grass, and weedy annual vegetation.

