

Final Reclamation Inspection

October 31, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 330114

Inspection Document #: 718801020

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: ANTENNA FEDERAL #31-36

Location ID: 330114



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards as weedy annual vegetation including russian thistle (*Salsola tragus*) was observed across the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos

Location Name: ANTENNA FEDERAL #31-36

Location ID: 330114



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos

Location Name: ANTENNA FEDERAL #31-36

Location ID: 330114



Photo 5. Photo taken of ground cover at the location. Photo illustrates weedy annual vegetation including russian thistle (*Salsola tragus*).



Photo 6. Photo taken of the access road to the well location, facing northwest. Photo illustrates that final reclamation activities have taken place along the access road.



Inspection Photos
Location Name: ANTENNA FEDERAL #31-36
Location ID: 330114



Photo 7. Photo taken of the reference area to the location, north of the location, facing east. Photo illustrates perennial grass.

