

| api_number   | well_common_name | date_test  | bh_pressure | bh_pressure_inter | casing_pressure | tubing_pressure | line_pressure |
|--------------|------------------|------------|-------------|-------------------|-----------------|-----------------|---------------|
| 05-045-09961 | RMV 170-19       | 8/11/2025  | 146         |                   | 144             | 135             | 104           |
| 05-045-09961 | RMV 170-19       | 7/17/2025  | 157         | 0                 | 145             | 136             | 107           |
| 05-045-09961 | RMV 170-19       | 6/2/2025   | 160         | 0                 | 141             | 135             | 104           |
| 05-045-09961 | RMV 170-19       | 5/13/2025  | 151         | 0                 | 142             | 137             | 105           |
| 05-045-09961 | RMV 170-19       | 4/15/2025  | 154         | 0                 | 141             | 136             | 108           |
| 05-045-09961 | RMV 170-19       | 3/5/2025   | 161         | 0                 | 139             | 134             | 103           |
| 05-045-09961 | RMV 170-19       | 2/5/2025   | 161         | 0                 | 141             | 136             | 106           |
| 05-045-09961 | RMV 170-19       | 1/16/2025  | 163         |                   | 139             | 134             | 103           |
| 05-045-09961 | RMV 170-19       | 12/12/2024 | 159         | 0                 | 141             | 135             | 104           |
| 05-045-09961 | RMV 170-19       | 11/18/2024 | 153         | 0                 | 143             | 136             | 108           |
| 05-045-09961 | RMV 170-19       | 10/15/2024 | 168         | 0                 | 147             | 140             | 108           |
| 05-045-09961 | RMV 170-19       | 9/25/2024  | 160         | 0                 | 147             | 139             | 104           |
| 05-045-09961 | RMV 170-19       | 8/12/2024  | 166         | 0                 | 150             | 142             | 109           |

