

State of Colorado  
Energy & Carbon Management Commission



Document Number:  
404446358

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Date Received:  
11/21/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 75000  
Name of Operator: BYRD\* CAROL W TRUSTEE OF CAROL W BYRD TRUST  
Address: 8163 E 131 RD  
City: WETUMKA State: OK Zip: 74883-6227

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Kyle Waggoner</u>		<u>kyle.waggoner@state.co.us</u>
<u>Krystal Heibel</u>		<u>krystal.heibel@state.co.us</u>
<u>Carol Byrd</u>		<u>cwbyrd@oilandgasroyalties.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 709100335  
Inspection Date: 06/26/2024 FIR Submit Date: 07/09/2024 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BYRD\* CAROL W TRUSTEE OF CAROL W BYRD TRUST Company Number: 75000  
Address: 8163 E 131 RD  
City: WETUMKA State: OK Zip: 74883-6227

LOCATION - Location ID: 317042

Location Name: LYLE CHANDLER-62N49W Number: 10NESE County: \_\_\_\_\_  
Qtrqr: NESE Sec: 10 Twp: 2N Range: 49W Meridian: 6  
Latitude: 40.152294 Longitude: -102.834362

FACILITY - API Number: 05-121-00 Facility ID: 102612

Facility Name: LYLE CHANDLER Number: \_\_\_\_\_  
Qtrqr: NESE Sec: 10 Twp: 2N Range: 49W Meridian: 6  
Latitude: 40.152294 Longitude: -102.834362

CORRECTIVE ACTIONS:

1 CA# 196623

Corrective Action: Repair berms or other secondary containment devices around pit. Date: 07/26/2024

Response: CA COMPLETED Date of Completion: 11/21/2025

Operator Comment: Holes in berms have been repaired. see photos

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**2** CA# 196624

Corrective Action: Prevent any unauthorized discharge from tank. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 07/26/2024

Response: CA COMPLETED

Date of Completion: 11/21/2025

Operator  
Comment:

Any unauthorized discharge from tank has been prevented by securely fastening all valves, pipes, and fittings. Equipment is inspected at regular intervals.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**3** CA# 196625

Corrective Action: Comply with Rule 606

Date: 07/12/2024

Response: CA COMPLETED

Date of Completion: 11/21/2025

Operator  
Comment:

Unused equipment has been removed from site

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**4** CA# 196626

Corrective Action: Install sign to comply with Rule 605.e.

Date: 09/08/2024

Response: CA COMPLETED

Date of Completion: 11/21/2025

Operator  
Comment:

Tank capacity has been added to tank. See photos

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lauren Glazier

Signed: \_\_\_\_\_

Title: Consultant

Date: 11/21/2025 11:15:15 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
404446391	Photos

Total Attach: 1 Files