



Inspection Photos  
Operator: Smith Energy  
Location Name: McCREATH A 1  
API: 05-121-09382



1. Wellhead and lease sign

2. Meter shed and VGS shed


Inspection Photos  
Operator: Smith Energy  
Location Name: McCREATH A 1  
API: 05-121-09382



3. Metal shed for VGS

4. Metal shed on north side of west pit

Inspection Photos  
Operator: Smith Energy  
Location Name: McCREATH A 1  
API: 05-121-09382



5. East pit has free fluid at time of inspection

6. Looking south at both pits