

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH UNIT-66S100W/1NWSE

Location ID: 323847

Date: 11/18/2025



Location – Photo #01591



Location – Photo #01592

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH UNIT-66S100W/1NWSE

Location ID: 323847

Date: 11/18/2025



Location – Photo #01588



No Erosion Controls Installed at Stream Crossing – Photo #01594