

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 31-33 Pad

Location ID: 335364



Photo # 4629 From entrance to location



Photo # 4630 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 31-33 Pad

Location ID: 335364



Photo # 4631 Location



Photo # 4632 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 31-33 Pad

Location ID: 335364



Photo # 3935 From inspection/audit 708907782 conducted on 10/29/2025 - Open ended load line

Photo # 4635 Open ended load line

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 31-33 Pad

Location ID: 335364



Photo # 4636 Debris