

Inspection Photos

API: 017-07777

Operator: **ANADARKO E&P ONSHORE LLC**

Inspection Date: 11/17/2025

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east. The beginning portion of the access road was not reclaimed and the fence is not reinstated to the original fence line.



Inspection Photos



Photo 2. The cattleguard has not been removed.



Inspection Photos



Photo 3. Facing east at the location. The native vegetation has fully re-established.



Inspection Photos



Photo 4. Facing west at the location. The native vegetation has fully re-established.

