

Final Reclamation Inspection

November 6, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 331201

Inspection Document #: 718801038

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HSR-KRAUSE #14-28A
Location ID: 331201



Photo 1. Photo taken of the well location, facing north. Photo illustrates that crop revegetation at the well location meets Rule 1004 standards.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos
Location Name: HSR-KRAUSE #14-28A
Location ID: 331201



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos
Location Name: HSR-KRAUSE #14-28A
Location ID: 331201



Photo 5. Photo taken of the well location, facing southeast. See comments under Photo 1.



Photo 6. Photo taken of the reference area to the well location, northwest of the location, facing northwest. Photo illustrates corn cropland.



Inspection Photos
Location Name: HSR-KRAUSE #14-28A
Location ID: 331201



Photo 7. Photo taken of the tank battery location, facing west. Photo illustrates that final reclamation activities do not appear to have taken place as gravel, bare ground, and weedy annual vegetation were observed across the location.



Photo 8. Photo taken of the tank battery location, facing north. See comments under Photo 7.



Inspection Photos
Location Name: HSR-KRAUSE #14-28A
Location ID: 331201



Photo 9. Photo taken of the tank battery location, facing southwest. See comments under Photo 7.



Photo 10. Photo taken of the tank battery location, facing east. See comments under Photo 7.

Inspection Photos

Location Name: HSR-KRAUSE #14-28A

Location ID: 331201



Photo 11. Photo taken of ground cover at the tank battery location. Photo illustrates gravel and weedy annual vegetation, including russian thistle (*Salsola tragus*).



Photo 12. Photo taken of the reference area to the tank battery location, south of the location, facing southwest. Photo perennial grass and sand sagebrush (*Artemisia filifolia*).

