

# Inspection Photos

API: 017-06480

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 11/17/2025

County: Cheyenne



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing east along the access road. The road has been regraded. The disturbed area where vehicles were driving will need to be decompacted and reclaimed.



## Inspection Photos



**Photo 2.** Facing east along the access road. The road has been regraded. This disturbed area where vehicles were driving will need to be decompacted and reclaimed.



## Inspection Photos



**Photo 3.** Facing east along the access road. The road has been regraded. The disturbed area where vehicles were driving will need to be decompacted and reclaimed.



## Inspection Photos



**Photo 4.** Facing west along the access road toward the wellsite.



## Inspection Photos



**Photo 5.** Facing west toward the wellsite.

