

# Inspection Photos

API: 071-09654

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 11/24/2025

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west toward the location.



## Inspection Photos



**Photo 2.** Facing toward the fill slope which is stabilized with vegetation.



## Inspection Photos



**Photo 2.** Well sign is posted on meter shed..



## Inspection Photos



**Photo 4.** Facing toward the wellhead.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:071-09654 | Date: 11/24/2025