

WELL NAME: NEW ELK 25-02, API #: 071-09474, INSP. # 716301764

719-497-0446
or EMERGENCY 911



NEW ELK 25-02
API# 05-071-09474
NE/NE 25-33S-68W
LAT. 37.148192
LONG. -104.944358

Network: Nov 25, 2025 at 2:22:44 PM MST
Local: Nov 25, 2025 at 2:22:44 PM MST
+37.148273, -104.944269

PHOTO 1: WELL SIGN



PHOTO 2: LOCATION.

Network: Nov 25, 2025 at 2:19:45 PM MST
Local: Nov 25, 2025 at 2:19:45 PM MST
+37.148638, -104.944565
Los Animas County



Network: Nov 25, 2025 at 2:20:29 PM MST
Local: Nov 25, 2025 at 2:20:30 PM MST
+37.148198, -104.944441
Los Animas County

PHOTO 3: WELLHEAD AND EQUIPMENT.



PHOTO 4: WEEDS NOT MAINTAINED NEAR WELLHEAD AND METER HOUSE. MAINTAIN WEEDS PER FULE 606. CA DATE 12-8-2025.



PHOTO 5: AREA OF IMPACTED SOIL NEAR COMPRESSOR SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. THIS IS THE 2ND NOTICE FOR THIS CA, IMMEDIATE ACTION IS REQUIRED.





PHOTO 6: OILY WASTE IN COMPRESSOR SKID. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. 24 HOURS TO DRAIN OILY WASTE, 10 DAYS TO REPAIR LEAKING EQUIPMENT.



Network:Nov 25, 2025 at 2:22:30 PM MST
Local:Nov 25, 2025 at 2:22:30 PM MST
+37.148219,-104.944320
Los Animas County

PHOTO 7: OILY WASTE IN COMPRESSOR SKID. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002.(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 11-26-2025.