

Audit Photos

Location Name: QB ENERGY OPERATING LLC, HYRUP-68S96W/11NESW

Location ID: 312702

Date: 11/20/2025



Location Overview – Photo #01638



Location – Photo #01639

Audit Photos

Location Name: QB ENERGY OPERATING LLC, HYRUP-68S96W/11NESW

Location ID: 312702

Date: 11/20/2025



Location – Photo #01642



Location – Photo #01640

Audit Photos

Location Name: QB ENERGY OPERATING LLC, HYRUP-68S96W/11NESW

Location ID: 312702

Date: 11/20/2025



Lack of Stabilization – Photo #01641



Insufficient Tracking BMPs – Photo #01643