

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION

Receive Date:

11/26/2025

Document Number:

404452255

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: <u>47120</u>	Contact Person: <u>Dane Olson</u>
Company Name: <u>KERR MCGEE OIL & GAS ONSHORE LP</u>	Phone: <u>(307) 760-5319</u>
Address: <u>P O BOX 173779</u>	Fax: <u>()</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80217-3779</u>	Email: <u>Dane_Olson@oxy.com</u>

Identification Information

API Number: <u>05 - 123-21613</u>	ECMC Facility ID: <u>269070</u>	Initial Form 19 or 27 Document number: _____
Facility Name: <u>KUNTZ</u>	Facility Number: <u>5-23</u>	Facility Type: <u>WELL</u>
Location QtrQtr: <u>SWNW</u>	Section: <u>23</u>	Township: <u>3N</u>
	Range: <u>66W</u>	Meridian: <u>6</u>
	County: <u>WELD</u>	Field Name: <u>WATTENBERG</u>
Federal, Indian or State Lease Number: _____		

Information Submitted By:

Company Name: <u>Absaroka Solutions</u>	Agent Name: <u>Jordan Fleming</u>	Title: <u>Environmental Professional</u>
Phone Number: <u>7202448469</u>	Email: <u>jordan.fleming@absarokasolutions.com</u>	

Rule 909.J Inspection Information

Date the Pit was Inspected _____

On inspection the Pit was: Unlined Lined Fenced Netted

Sample Location Information:

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: <u>269070</u>	Facility Name: <u>KUNTZ 5-23</u>	Facility Type: _____
Location: QtrQtr: <u>SWNW</u>	Sec: <u>23</u>	Twp: <u>3N</u>
	Range: <u>66W</u>	Meridian: <u>6</u>
County Name: <u>WELD</u>	Latitude: <u>40.212040</u>	Longitude: <u>-104.751020</u>

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: <u>131859</u>	Document Name: <u>Size of file in bytes: 17350</u>	File Name: <u>2025_09_04_BW_05_123_21613_BHD_SGS_ECM C_RSK.xlsx</u>
SampleType: _____	Matrix: _____	
Facility ID: <u>269070</u>	Sample ID: <u>672867</u>	Sample Name: <u>BW_05_123_21613_BHD</u>
	Sample Date: <u>09/04/2025</u>	
Collection Point: <u>BDH</u>	Matrix: <u>WATER</u>	Pre Post: <u>Bradenhead Water Sample</u>
Project Number: _____	Remediation Number: _____	Complaint Number: _____
		NOAV Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: <u>Accutest</u>
		Lab Sample ID: <u>DA75030-1</u>

Batch ID: 131862 Document Name: Size of file in bytes: 20042 File Name: 2025_09_04_SP_05_123_21613_C_Isotech_NG4_ECMC.xlsx

SampleType: _____ Matrix: _____

Facility ID: 269070 Sample ID: 672870 Sample Name: SP_05_123_21613_C Sample Date: 09/04/2025

Collection Point: PRDC Matrix: GAS Pre Post: Production Gas Sample

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: ISOTECH Lab Sample ID: 982608

Batch ID: 131861 Document Name: Size of file in bytes: 19999 File Name: 2025_09_04_SP_05_123_21613_BHD_Isotech_NG4_ECMC.xlsx

SampleType: _____ Matrix: _____

Facility ID: 269070 Sample ID: 672869 Sample Name: SP_05_123_21613_BHD Sample Date: 09/04/2025

Collection Point: BDH Matrix: GAS Pre Post: Bradenhead Gas Sample

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: ISOTECH Lab Sample ID: 982609

Batch ID: 131858 Document Name: Size of file in bytes: 30788 File Name: 2025_09_04_BW_05_123_21613_BHD_SGS_ECMC.xlsx

SampleType: _____ Matrix: _____

Facility ID: 269070 Sample ID: 672866 Sample Name: BW_05_123_21613_BHD Sample Date: 09/04/2025

Collection Point: BDH Matrix: WATER Pre Post: Bradenhead Water Sample

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: Accutest Lab Sample ID: DA75030-1

Batch ID: 131860 Document Name: Size of file in bytes: 19039 File Name: 2025_09_04_BW_05_123_21613_BHD_Trip_Blank_SGS_ECMC.xlsx

SampleType: _____ Matrix: _____

Facility ID: 269070 Sample ID: 672868 Sample Name: BW_05_123_21613_BHD_Trip_Blank Sample Date: 09/04/2025

Collection Point: TB Matrix: WATER Pre Post: Trip Blank

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: Accutest Lab Sample ID: DA75031-1

Sample Facility Attachment:
No Facility Attachment

Sample ECMC Well Related:

Sample ID	API Num	Well Name & Num	Sample Reason
672868	123-21613	KUNTZ 5-23	Trip Blank

General Comments

User Group	Comment	Comment Date
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system.	11/26/2025

Total: 1 comment(s)