

# Inspection Photos

Loc: 476137

Operator: **WILLIFORD ENERGY COMPANY**

Inspection Date: 11/17/2025

County: Cheyenne



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southeast toward the tank battery. The E&P waste stored at this area was removed however there is still a pile of loose material that could be remnants leftover.



## Inspection Photos



**Photo 2.** There are still oily impacted material around the tanks that have not been cleaned up.



## Inspection Photos



**Photo 3.** Oily impacts at pipe outlet.



**Photo 4.** Oily impacts around base of the tank.



## Inspection Photos



**Photo 5.** The gate at the south side of the location was left open and signs of cattle were inside the tank battery site.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 476137 | Date: 11/17/2025

## Inspection Photos



**Photo 6.** Facing west toward the area where new and additional spill recently occurred.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 476137 | Date: 11/17/2025

## Inspection Photos



**Photo 7.** There are still impacts and leaks occurring at the base of the tank at the south side of the location.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 476137 | Date: 11/17/2025

## Inspection Photos



**Photo 8.** There are still impacts and leaks occurring at the base of the tank at the south side of the location.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 476137 | Date: 11/17/2025