Audit Photos
Location Name: QB ENERGY OPERATING LLC, GASAWAY-66S99W/20NESE
Location ID: 324233
Date: 11/24/2025

Location Overview/Lack of Stabilization – Photo #01652

Location – Photo #01653

Audit Photos
Location Name: QB ENERGY OPERATING LLC, GASAWAY-66S99W/20NESE
Location ID: 324233
Date: 11/24/2025

Location/Lack of Stabilization – Photo #01656

Location – Photo #01654

Audit Photos
Location Name: QB ENERGY OPERATING LLC, GASAWAY-66S99W/20NESE
Location ID: 324233
Date: 11/24/2025

Lack of Stabilization – Photo #01657

Lack of Stabilization – Photo #01658

Audit Photos
Location Name: QB ENERGY OPERATING LLC, GASAWAY-66S99W/20NESE
Location ID: 324233
Date: 11/24/2025

Lack of Stabilization – Photo #01659

Insufficient Tracking BMPs – Photo #01660

Audit Photos
Location Name: QB ENERGY OPERATING LLC, GASAWAY-66S99W/20NESE
Location ID: 324233
Date: 11/24/2025

Lease Road Lacks Stabilization – Photo #01662

Lease Road Lacks Stabilization – Photo #01663