

Inspection Photos

11/21/2025

Operator: TEP Rocky Mountain LLC #96850

Location ID: 450340

Inspection Doc: 719200467

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 450340



Photo 1: Photos showing an overview of the lower and upper portions of the pad, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 450340



Photo 2: Photo showing an example of vehicle tracking and ponded water at the location entrance. Gravel is sparse in some areas. Comply with 1002.f. and maintain stormwater BMPs.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 450340



Photo 3: Photos showing examples of stormwater controls on the cut slope behind tank equipment; some are laden with sediment, reducing capacity. Erosion, rilling and degradation is occurring at others. Comply with 1002.f. and maintain stormwater BMPs.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 450340



Photo 4: Photos showing examples of the eastern interim area. The area appears to be dominated by cheatgrass and other weedy annuals. A follow-up inspection will be conducted during future growing seasons to determine compliance with 1003 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 450340



Photo 5: Photos showing examples of the northern and southern interim areas, respectively. Rubber rabbitbrush, crested wheatgrass and other perennial grass species have established. Northern and southern interim areas are progressing towards 1003 requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 450340



Photo 6: Photo showing an example of prickly Russian thistle, an undesirable annual weed, that is present along the margins of the working pad surface. Weed maintenance will be required on the working pad surface and within the interim areas in 2026.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources