

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH FEDERAL-66S100W/17SWSE

Location ID: 323836

Date: 11/25/2025



Location Overview – Photo #01718



Location – Photo #01719

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH FEDERAL-66S100W/17SWSE

Location ID: 323836

Date: 11/25/2025



Location – Photo #01720



Location – Photo #01721

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH FEDERAL-66S100W/17SWSE

Location ID: 323836

Date: 11/25/2025



Lack of Stabilization on Lease Road – Photo #01774

Lack of Stabilization on Lease Road – Photo #01775