

Inspection Photos

Facility Name: Kohlhoff AC 09-65HN/

Facility #: 483177



Photo #1

Kohlhoff AC 09-65HN Battery site

Inactive | Shut-down

Equipment documented: Fac. ID 483177



Photo #2

Kohlhoff AC 09-65HN Battery site

Inactive | Shut-down

Wellsite(s), Battery entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Facility Name: Kohlhoff AC 09-65HN/

Facility #: 483177



Photo #3

Kohlhoff AC 09-65HN Battery site

Inactive | Shut-down

*Crude Oil tank(s), Produced H₂O tank(s), vault(s);
SE corner*



Photo #4

Kohlhoff AC 09-65HN Battery site

Inactive | Shut-down

Separator(s), ECD(s)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Facility Name: Kohlhoff AC 09-65HN/

Facility #: 483177



Photo #5

Kohlhoff AC 09-65HN Battery site

Inactive | Shut-down

Battery signage



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Facility Name: Kohlhoff AC 09-65HN/

Facility #: 483177

Associated Well(s)	API	Location	Status
1. Kohlhoff AC 09-65HN	123-34901	427237	SI

Photo #6

Kohlhoff AC 09-65HN Battery site

Inactive | Shut-down

Associated well(s)

1: Shut-In | SI



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources