

# Inspection Photos

11/21/2025

**Operator:** QB Energy Operating LLC #10844

**Location ID:** 324238

**Inspection Doc:** 719200487

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 324238



**Photo 1:** Photos showing an overview of the location looking northeast (top left), north (top right) and the wellhead looking southwest (bottom left).



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 324238



**Photo 2:** Photos showing rilling and erosion is occurring on the northwestern portion of the location behind production tank equipment. Stormwater controls appear missing or insufficient; comply with 1002.f.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 324238



**Photo 3:** Photos showing an overview of the northern and southern interim areas, respectively. The interim areas are well-established and desirable, uniform and perennial vegetation is present. Overall, interim areas at the location are progressing towards 1003 reclamation requirements.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources