

Inspection Photos
Location: Big Timmer 32-19
Location ID: 308880
API # 05-071-08761



Photo 1 – Well Placard

Photo 2 – Wellhead and equipment

Inspection Photos
Location: Big Timmer 32-19
Location ID: 308880
API # 05-071-08761



Photo 3 – Meter house and equipment

Photo 4 – Pit Facility ID: 285086, tree in pit

Inspection Photos
Location: Big Timmer 32-19
Location ID: 308880
API # 05-071-08761



Photo 5 – Stained soils at base of engine skid

Photo 6 – Red hose not properly secured in tank

Inspection Photos
Location: Big Timmer 32-19
Location ID: 308880
API # 05-071-08761



Photo 7 – Drip near county road intersection.