

Inspection Photos

11/21/2025

Operator: QB Energy Operating LLC #10844

Location ID: 334625

Inspection Doc: 719200493

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334625



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334625



Photo 2: Photos showing an overview of the location looking east and west, respectively. Vehicle rutting and tracking is occurring on the working pad surface and gravel is sparse in areas. Comply with 1002.f. and maintain stormwater BMPs.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334625



Photo 3: Photos showing an overview of the northern and southern interim areas, respectively. Desirable, perennial and uniform vegetation is present. Interim areas at the location are progressing towards 1003 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334625



Photo 4: The area behind production equipment at the location is predominantly bare and is at risk of erosion and degradation. No stormwater issues were observed in this area during the time of inspection; however, additional stabilization efforts and/or reclamation efforts may be required in the future.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources