

Inspection Photos

11/21/2025

Operator: QB Energy Operating LLC #10844

Location ID: 324025

Inspection Doc: 719200495

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 324025



Photo 1: Photos showing an overview of the location looking southwest and northeast, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 324025



Photo 2: Photo showing an overview of the location looking west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 324025



Photo 3: Photo showing an example of vehicle rutting and tracking on the working pad surface. Comply with Rule 1002.f.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 324025



Photo 4: Photo showing an example of trash that is present on the southern interim area. Comply with Rule 606.d. and remove trash.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 324025



Photo 5: Photos showing an overview of the southern and southwestern interim areas, respectively. Desirable, perennial and uniform vegetation is present. Interim areas at the location are progressing towards 1003 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources