

Final Reclamation Inspection

August 26th, 2025

Operator: Kerr McGee Oil & Gas Onshore - 47120

Location ID: 330303

Inspection Document #: 714002812

Weld County, CO

Corey Mcdonough
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: HSR-Sekich #15-17

Location ID: 330303



Photo 1. NAIP aerial imagery (2009) illustrating the well location (red circle), associated tank battery location (blue polygon), and well access road location (black line). The tank battery is associated with the Sekich Multiwell pad under location ID #421013.



Inspection Photos

Location Name: HSR-Sekich #15-17

Location ID: 330303



Photo 2. NAIP aerial imagery (2023) illustrating the well location (red circle) and associated tank battery (blue polygon).



Inspection Photos

Location Name: HSR-Sekich #15-17

Location ID: 330303



Photo 3. Drone aerial imagery taken south of well location, facing north (displaying the well).





Photo 4. Drone aerial imagery taken west of well location, facing east (displaying the well).

Inspection Photos

Location Name: HSR-Sekich #15-17

Location ID: 330303



Photo 5. Drone aerial imagery taken north of well location, facing south (displaying the well and well access road). Crop vegetation at the well pad and access road appear consistent with adjacent reference areas.





Photo 6. Drone aerial imagery taken east of well location, facing west (displaying the well).

Inspection Photos

Location Name: HSR-Sekich #15-17

Location ID: 330303



Photo 7. Drone aerial imagery taken northeast of well location, facing southwest (displaying the well and presumed flow line).

