

Final Reclamation Inspection

August 27th, 2025

Operator: Kerr McGee Oil & Gas Onshore - 47120

Location ID: 330304

Inspection Document #: 714002822

Weld County, CO

Corey Mcdonough
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: HSR-Sekich 16-17

Location ID: 330304



Photo 1. NAIP aerial imagery (2009) illustrating the well location (red circle), associated tank battery location (blue polygon), and well access road. Tank battery is associated with the HSR Sekich 9-17 well API #123-18820 under location ID #330297.



Inspection Photos

Location Name: HSR-Sekich 16-17

Location ID: 330304




Photo 2. NAIP aerial imagery (2023) illustrating the well location (red circle) and associated tank battery (blue polygon).



Inspection Photos

Location Name: HSR-Sekich 16-17

Location ID: 330304



Photo 3. Drone aerial imagery taken south of well location, facing north (displaying the well, access road, TB, and presumed flowline). Crop vegetation at the well pad and access road appear consistent with adjacent reference areas.



Inspection Photos

Location Name: HSR-Sekich 16-17

Location ID: 330304



Photo 4. Drone aerial imagery taken west of well location, facing east (displaying the well).



Inspection Photos

Location Name: HSR-Sekich 16-17

Location ID: 330304



Photo 5. Drone aerial imagery taken north of well location, facing south (displaying the well and access road).



Inspection Photos

Location Name: HSR-Sekich 16-17

Location ID: 330304



Photo 6. Drone aerial imagery taken east of well location, facing west (displaying the well).



Inspection Photos

Location Name: HSR-Sekich 16-17

Location ID: 330304



Photo 7. Drone aerial imagery taken southwest of well location, facing northeast (displaying the well, TB (obscured by trees), access road, and presumed flowline location).

