

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH FEDERAL-66S100W/29SWNE

Location ID: 323852

Date: 11/25/2025



Location Overview – Photo #01747



Location – Photo #01748

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH FEDERAL-66S100W/29SWNE

Location ID: 323852

Date: 11/25/2025



Nov 25, 2025 at 10:43:42
+39.507621,-108.575232
De Beque CO 81630
United States



Nov 25, 2025 at 10:43:16
+39.507541,-108.575036
De Beque CO 81630
United States

Location – Photo #01751

Location – Photo #01750

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH FEDERAL-66S100W/29SWNE

Location ID: 323852

Date: 11/25/2025



No BMPs or Erosion Controls at Stream Crossing – Photo #01731



No BMPs or Erosion Controls at Stream Crossing – Photo #01732

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH FEDERAL-66S100W/29SWNE

Location ID: 323852

Date: 11/25/2025



Insufficient Erosion Controls on Lease Road – Photo #01754