

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH-66S100W/28NENW

Location ID: 324225

Date: 11/25/2025



Location Overview – Photo #01760



Location – Photo #01761

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH-66S100W/28NENW

Location ID: 324225

Date: 11/25/2025



Nov 25, 2025 at 10:55:34
+39.508373,-108.560500
18956-19420 CR-204
De Beque CO 81630
United States



Nov 25, 2025 at 10:54:47
+39.508404,-108.560568
18957-19421 CR-204
De Beque CO 81630
United States

Location – Photo #01765

Location – Photo #01762

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH-66S100W/28NENW

Location ID: 324225

Date: 11/25/2025



Location – Photo #01766



Lack of Stabilization/Insufficient Erosion Controls on Lease Road – Photo #01774

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CEDAR BENCH-66S100W/28NENW

Location ID: 324225

Date: 11/25/2025



Lack of Stabilization/Insufficient Erosion Controls on Lease Road – Photo #01775