

Inspection Photos

11/25/2025

Operator: QB Energy Operating LLC #10844

Location ID: 323909

Inspection Doc: 719200505

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 323909



Photo 1: Photos showing an overview of the location looking northeast and southwest, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 323909



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 323909



Photo 3: At the time of inspection, tank equipment at the location does not appear to be in use. Comply with Rule 606.a. and remove unused equipment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 323909



Photo 4: Photos showing an example of vegetative debris that appears to have been removed from the working pad surface and pushed to the margins of the interim areas. Comply with Rule 606.d. and remove vegetative debris.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 323909



Photo 5: Photos showing an example of debris, such as barbed wire, wooden posts and steel cable is present in the northernmost portion of the location. Removal is required; comply with Rule 606.d.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 323909



Photo 6: Photos showing an example of the western and northern interim areas, respectively. Desirable, perennial and uniform vegetation has established. Interim areas at the location are progressing towards 1003 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources