

Inspection Photos

September 10th, 2025

Operator: Noble Energy Inc.

Location ID: 328203

Inspection Document #: 714002574

County: Weld

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Gunther B18-1
Location ID: 328203




Photo 1. Aerial view of the well pad (highlighted in red), Access road (highlighted in yellow) and Tank Battery (highlighted in blue). Note: Tank battery is associated with its own location ID #485933.

Inspection Photos
Location Name: Gunther B18-1
Location ID: 328203



Photo 2. Aerial view of the well pad and tank battery taken with a drone during the time of the inspection from the southern edge facing north.