

# Interim Reclamation and Stormwater Inspection

November 24, 2025

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 333126

Well Name: MEREDITH #2

Inspection Document #: 718601208

Weld County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: MEREDITH #2  
Location ID: 333126



**Photo 1.** Looking west at the wellhead. The area around the wellhead has been mowed.



**Photo 2.** Looking south at the tank battery located to the east of the wellhead. Undesirable weeds such as kochia are unmanaged on location and touching equipment.



Inspection Photos  
Location Name: MEREDITH #2  
Location ID: 333126



**Photo 3.** Looking east across the south side of the location. See photo 2 comments.



**Photo 4.** Photo taken at the separator on the tank battery. Undesirable weeds are unmanaged on location. Weeds are touching equipment.

