

Final Reclamation and Stormwater Inspection

November 24, 2025

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 318195

Well Name: GRANT #2

Inspection Document #: 718601206

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: GRANT #2
Location ID: 318195



Photo 1. Picture taken at the southwest side of the location. Electric meter and post remain.



Photo 2. Looking west across the location. Location is bare soil and gravel. Some undesirable weeds such as a kochia are present. Stormwater erosion channels are visible.



Inspection Photos
Location Name: GRANT #2
Location ID: 318195



Photo 3. Looking west down the north side of the location. Sediment appears to be moving to this area of the location through stormwater erosion.



Photo 4. Photo taken on the north side of the location. It appears that sediment is leaving the location through this drain in the curb.