

# Inspection Photos

11/25/2025

Operator: QB Energy Operating LLC #10844

Location ID: 334667

Inspection Doc: 719200513

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334667



**Photo 1:** Photos showing an overview of the location looking north and south, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334667



**Photo 2:** Photos showing an overview of the location looking east and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334667



**Photo 3:** Photos showing a sediment trap on the northern edge of the working pad surface. Erosion, rilling and subsidence is occurring. Comply with 1002.f. and maintain stormwater BMPs.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334667



**Photo 4:** Photos showing the eastern and northern interim areas, respectively. Desirable, perennial and uniform vegetation is present. Interim areas are progressing towards 1003 reclamation requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334667



**Photo 5:** Vehicle rutting is present throughout the working pad surface and gravel is sparse in some areas. Comply with 1002.f.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334667



**Photo 6:** A stormwater control on the western edge of the working pad surface appears to be laden with sediment and has reached capacity. Comply with 1002.f. and implement or maintain stormwater BMPs.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources