

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
404330145
Receive Date:
08/27/2025

Report taken by:
Abdul Elnajdi

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECOM is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: <u>NOBLE ENERGY INC</u>	Operator No: <u>100322</u>	Phone Numbers Phone: <u>(970) 786-0202</u> Mobile: <u>()</u>
Address: <u>1099 18TH STREET SUITE 1500</u>		
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>
Contact Person: <u>Kristofer Shepherd</u>	Email: <u>Kristofer.Shepherd@chevron.com</u>	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 30272 Initial Form 27 Document #: 403417714

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: _____

SITE INFORMATION

No Multiple Facilities

Facility Type: <u>WELL</u>	Facility ID: _____	API #: <u>123-18860</u>	County Name: <u>WELD</u>
Facility Name: <u>UPV 5-5H3</u>	Latitude: <u>40.429766</u>	Longitude: <u>-104.467816</u>	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: <u>SWNW</u>	Sec: <u>5</u>	Twp: <u>5N</u>	Range: <u>63W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

SITE CONDITIONS

General soil type - USCS Classifications SW Most Sensitive Adjacent Land Use Grassland
 Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? No
 Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

Well Within Pronghorn Winter Concentration Area HPH
No other potential receptors are located within 1/4 mile of the Site.
Above distances are approximations.

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- E&P Waste** **Other E&P Waste** **Non-E&P Waste**
- Produced Water Workover Fluids
- Oil Tank Bottoms
- Condensate Pigging Waste
- Drilling Fluids Rig Wash
- Drill Cuttings Spent Filters
- Pit Bottoms
- Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	GROUNDWATER	NA	Lab analysis and Field Screening, if encountered
No	SOILS	Refer to Tables and Figures	Field Screening and Lab Analysis

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Pursuant to ECMC Rule 911 a site investigation was conducted pertaining to the UPV 05-05H3 wellhead cut and cap and flowline removal. Approximately 1610' of flowline was removed. The ECMC was updated in a supplemental Form 27 if a portion of the flowline is abandoned-in-place due to field constraints. The wellhead was cut and capped per ECMC rules. Additionally, soil samples were field screened at the N-E-S-W sides of the wellhead. Soil samples were taken along the flowline at any points of material change and/or hammer unions, directional changes, as well as at the bell holes on either side of a waterway. The Flowline Pre-Abandonment Notice Document number was included under Related Forms.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

A grab soil sample was collected at the base of the excavation or the area showing the highest degree of impact during field screening activities at the wellhead excavation. Additionally, soil samples were field screened at the N-E-S-W sides of the wellhead. Soil samples will be taken along the flowline at any points of material change and/or hammer unions, directional changes, as well as at the bell holes on either side of a waterway. Soil samples were analyzed by a certified laboratory for TPH (total volatile [C6-C10] and extractable [C10-C36] hydrocarbons) organic compounds in soil per ECMC Table 915-1, and EC, SAR, pH, and boron. All samples collected were analyzed by a certified laboratory using approved ECMC laboratory analysis methods

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

If groundwater is encountered during the site investigation a grab groundwater will be collected and analyzed for full Table 915-1 organic and inorganic constituents in groundwater (Benzene, Toluene, Ethylbenzene, Total Xylenes (BTEX), naphthalene, 1,2,4-Trimethylbenzene, 1,3,5-Trimethylbenzene, Chloride ion, Sulfate ion and Total Dissolved Solids (TDS).

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

Visual inspection along the flowline and at the wellhead and separator areas occurred during abandonment activities. Field personnel field screened all disturbed areas using visual and olfactory senses to determine if laboratory confirmation sampling was required. The applicable ECMC Closure Checklists were utilized and filled out during the abandonment process. A photolog was attached.

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 3

Number of soil samples exceeding 915-1 0

Was the areal and vertical extent of soil contamination delineated? No

Approximate areal extent (square feet) 0

NA / ND

-- Highest concentration of TPH (mg/kg) 27.7

-- Highest concentration of SAR 1.36

BTEX > 915-1 No

Vertical Extent > 915-1 (in feet) 0

Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? Yes

Depth to groundwater (below ground surface, in feet)

Number of groundwater monitoring wells installed

Number of groundwater samples exceeding 915-1

Highest concentration of Benzene (µg/l)

Highest concentration of Toluene (µg/l)

Highest concentration of Ethylbenzene (µg/l)

Highest concentration of Xylene (µg/l)

Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected

 Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Thirty background soil samples were collected from an area not impacted by oil and gas development. The samples were obtained at depths and within lithologies comparable to those of the confirmation soil samples collected at the site. All samples were analyzed for metals listed in Table 915-1, as well as soil suitability parameters relevant to reclamation, including pH, electrical conductivity (EC), sodium adsorption ratio (SAR), and boron concentrations. Analytical results from the background samples indicated elevated levels of pH, EC, arsenic (As), barium (Ba), and selenium (Se).

Background Soil Sample Analysis (mg/kg)

Total pH: Max = 9.06
Total EC: Max = 8.54
Total As: Max*1.25 = 5.82
Total Ba: Max*1.25 = 107
Total Se: Max*1.25 = 0.708

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

Is further site investigation required?

Per the COA issued under Document Number 403739326 and as part of Chevron's Data Integrity review for projects associated with Eagle Environmental, all point-of-compliance soil samples will be recollected in accordance with the approved Form 27 Site Investigation Plan. These samples will be analyzed for the full suite of Table 915-1 constituents.

Specifically, sample location WH-FS-01 @6', originally collected during wellhead cut and cap operations on February 7, 2024, will be resampled at the same depth and analyzed for the full Table 915-1 parameter list. Additional local background samples will also be collected to further characterize native soil conditions.

If the resample results comply with Table 915-1 standards, a No Further Action (NFA) request will be submitted. Background data will continue to be used to support any exceedances, where applicable. Analytical results from the resample and background samples will be reported in a subsequent Form 27.

Please refer to the attached Site Investigation Plan for proposed resample and additional background sample locations.

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

No source was generated.

REMEDATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

NA

Soil Remediation Summary

In Situ

Ex Situ

- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Air sparge / Soil vapor extraction
- _____ Natural Attenuation
- _____ Other _____

- _____ Excavate and offsite disposal
- _____ If Yes: Estimated Volume (Cubic Yards) _____
- _____ Name of Licensed Disposal Facility or ECMC Facility ID # _____
- _____ Excavate and onsite remediation
- _____ Land Treatment
- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Other _____

Groundwater Remediation Summary

- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Air sparge / Soil vapor extraction
- _____ Natural Attenuation
- _____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

If groundwater is encountered during the site investigation a grab groundwater will be collected and analyzed for full Table 915-1 organic and inorganic constituents in groundwater (Benzene, Toluene, Ethylbenzene, Total Xylenes (BTEX), naphthalene, 1,2,4-Trimethylbenzene, 1,3,5-Trimethylbenzene, Chloride ion, Sulfate ion and Total Dissolved Solids (TDS).

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

Quarterly Semi-Annually Annually Other

Request Alternative Reporting Schedule:

Semi-Annually Annually Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report

Other Supplemental Site Investigation Data Submittal & Supplemental Site Investigation Proposal _____

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Noble intends to directly address the costs of remediation at the locations as part of our asset retirement obligation process and operations. Noble has general liability insurance (policy MWZZ316714 and MWZX316724) and financial assurance in compliance with ECMC rules. Records are available on the ECMC's website. The cost for remediation is an estimate only, costs may change upwards or downward based on site-specific information. Noble makes no representation or guarantees as to the accuracy of the estimate.

Operator anticipates the remaining cost for this project to be: \$ 50000 _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

ECMC Disposal Facility ID #, if applicable: _____

Non-ECMC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

ECMC Disposal Facility ID #, if applicable: _____

Non-ECMC Disposal Facility: _____

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

Compliant with Rule 913.h.(1).

Compliant with Rule 913.h.(2).

Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? Yes

Does the previous reply indicate consideration of background concentrations? Yes

Does Groundwater meet Table 915-1 standards? Yes

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be in accordance with ECMC 1000 Series Rules.

Is the described reclamation complete? Yes

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. 10/31/2025

Proposed date of completion of Reclamation. 06/30/2027

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 05/11/2023

Actual Spill or Release date, or date of discovery. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 04/03/2024

Proposed site investigation commencement. 07/01/2023

Proposed completion of site investigation. 03/31/2026

REMEDIAL ACTION DATES

Proposed start date of Remediation. _____

Proposed date of completion of Remediation. _____

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

The implementation schedule has been changed due to the necessity for supplemental site investigation activities adjacent to the former UPV 5-5H3 wellhead. The proposed site investigation will be completed following the approval of this form.

OPERATOR COMMENT

This Form 27 is submitted as a Q3 2025 timeline update for the former UPV 5-5H3 wellhead and flowline location. It includes secured wellhead decommissioning results, supplemental site investigation findings, and proposes an additional supplemental site investigation.

Per the COA issued under Document Number 403810355, sample locations FL01@5.0' and FL08@5.0', originally collected during flowline decommissioning activities on April 2, 2024, were submitted outside the required temperature preservation range. To confirm the initial analytical data, both locations were resampled on May 7, 2025, and analyzed for the full ECMC Table 915-1 suite. The resample results confirmed the absence of organic constituents above Groundwater Protection Soil Screening Levels and showed that all parameters were below ECMC Soil Suitability for Reclamation standards.

However, arsenic and selenium concentrations were above Table 915-1 standards yet remained below 1.25 times the maximum background concentration for each corresponding constituent. Therefore, it is concluded that these elevated levels are attributable to native soil conditions.

Additionally, per the COA issued under Document Number 403739326 and as part of Chevron's Data Integrity review for projects associated with Eagle Environmental, all point-of-compliance soil samples will be recollected in accordance with the approved Form 27 Site Investigation Plan and analyzed for the full Table 915-1 suite.

Specifically, sample location WH-FS-01@6', originally collected during wellhead cut and cap operations on February 7, 2024, will be resampled at the same depth and analyzed for the full Table 915-1 parameter list. Additional local background samples will also be collected to further characterize native soil conditions.

If the resample data comply with Table 915-1 standards, a No Further Action (NFA) request will be submitted. Background data will continue to be used to support any exceedances, where applicable.

Please refer to the site investigation activities outlined in the proposed Site Investigation Report workplan and the attached Site Investigation Plan for sample locations. The operator will complete the additional site investigation activities as proposed, following approval of this Form 27.

Based on currently available data, this project is not affected by data integrity irregularities and is not associated with the operator's data integrity review process and its Rule 525.e. Voluntary Disclosure. As part of its data integrity review process, the operator requested the lab protect the laboratory analytical reports from subsequent unauthorized modification by anyone outside the lab, which resulted in the lab reissuing the original reports with additional protections (Reissued Reports). The Reissued Report(s) received directly from the lab on February 13, 2025 (Origins) and March 31, 2025 (Summit) include [if Origins] a watermark confirming both the laboratory representative who reissued the report and the date and time of the reissuance or [if Summit] the application of a Digital ID/Verified Certification (lock) to support reissuance. The metadata associated with this Reissued Reports also includes the lab representative's name, the date and time the laboratory reissued the reports, and an explanation for the reports reissuance. The Reissued Reports are attached to this submission.

In the event additional responsive information is received or discovered that would suggest this project should be incorporated into the ongoing data integrity review process associated with Operator's Rule 525.e. Voluntary Disclosure, Operator will update and/or amend the statements in this submission and provide any new or revised data or other information.

Quarterly reporting will be conducted until closure criteria are achieved for the remediation project. The results of the supplemental site investigation will be submitted on a subsequent Form 27.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Jeff Griggs

Title: Consultant

Submit Date: 08/27/2025

Email: jeffg@fremontenv.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: Abdul Elnajdi

Date: 12/05/2025

Remediation Project Number: 30272

COA Type

Description

0 COA	
-------	--

ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num

Name

404330145	INVESTIGATION/REMEDATION WORKPLAN (SUPPLEMENTAL)
404330245	LABORATORY ANALYTICAL REPORT
404330247	LABORATORY ANALYTICAL REPORT
404330252	LABORATORY ANALYTICAL REPORT
404330253	SITE INVESTIGATION REPORT
404330255	SITE INVESTIGATION REPORT

404330256	SITE INVESTIGATION PLAN
404330257	LABORATORY ANALYTICAL REPORT
404462165	FORM 27-SUPPLEMENTAL-SUBMITTED

Total Attach: 9 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)