

Inspection Photos

September 11th, 2025

Operator: Noble Inspection Photos

Location ID: 329830

Inspection Document #: 714002578

County: Weld

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Anderson 12-27
Location ID: 329830



Photo 1. Aerial view of the Well Pad (highlighted in red), Access Road (highlighted in black) and Tank Battery (highlighted in Blue). Note: Tank battery is associated with the Bohlender 1 well API #123-11984 under location ID #322746.

Inspection Photos
Location Name: Anderson 12-27
Location ID: 329830



Photo 2. Aerial view of the well pad and access road taken with a drone during the time of the inspection from the Southern edge facing North. Note: Crop vegetation at the well pad and access road appear consistent with adjacent reference areas.