

Inspection Photos

11/25/2025

Operator: QB Energy Operating LLC #10844

Location ID: 334637

Inspection Doc: 719200517

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334637



Photo 1: Photos showing an overview of the location looking northeast and southwest, respectively. Vehicle tracking is present on the working pad surface and gravel is sparse in some areas. Maintenance is recommended.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334637



Photo 2: Photos showing an overview of the location looking southeast and northwest, respectively. Vehicle tracking is present on the working pad surface and gravel is sparse in some areas. Maintenance is recommended.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334637



Photo 3: Photos showing the secondary containment liner at tank equipment is no longer sufficiently impervious. Comply with Rile 603.o.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334637



Photo 4: Photos showing an overview of the northwestern and southern interim areas, respectively. Desirable, uniform and perennial vegetation is present. The location is progressing towards 1003 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources