

Inspection Photos  
Location Name: Graham Unit 1  
Location ID: 318156



Photo 1 Location.

Photo 2 Tall dead vegetation around the Wellhead is snow covered.

Inspection Photos  
Location Name: Graham Unit 1  
Location ID: 318156




Photo 3 Wellsite sign, Tall dead vegetation around the pumpjack is snow covered.

Photo 4 Tall dead vegetation around Pumpjack is snow covered.