

Inspection Photos
Location Name: Just Unit 1
Location ID: 317959




Photo 1 Tall dead vegetation along location access rd. is snow covered.



Photo 2 Tall dead vegetation around the Wellsite is snow covered.

Inspection Photos
Location Name: Just Unit 1
Location ID: 317959



Photo 3 Wellsite sign, Tall dead vegetation around the pumpjack is snow covered.

Photo 4 Tall dead vegetation around Pumpjack is snow covered.

Inspection Photos
Location Name: Just Unit 1
Location ID: 317959



Photo 5 Tall dead vegetation around the wellhead is snow covered.