

Inspection Photos
Location Name: Graham unit 2
Location ID: 336415



Photo 1 Tall dead vegetation along location access rd. is snow covered.



Photo 2 Wellsite.

Inspection Photos
Location Name: Graham unit 2
Location ID: 336415



Photo 3 Well site sign.



Photo 4 Pumpjack.

Inspection Photos
Location Name: Graham unit 2
Location ID: 336415



Photo 5 Wellhead.