WELL SITE INSPECTION FORM

Well Name Ham #2 API Number 05 - 115 - 6002

Operator E. Lyle Johnson Permit # 67-443

Location NWSW/7-10N-47W County Sedgewick

Field Red Lion Inspector R. VanDuckle

AL/PA/DA Inspection Results: Well Status:

Pass(Y)____ Fail(N) ↘ Date 1-16-91 FN____ FD____ WO____ PR____ SI____

==========

Date of Inspection Before/During Drilling_____

Surf. Csg. Size____ Setting Depth_____ Cmt. Vol._____ WOC time_____

Consistent with APD casing Program? YES_____ NO____ Returns_____

Rig_____ BOP'S_____ Contact_____

Date of Inspection Before/During/After Completion_____

Prod. Csg. Set?_____ Completion Rig/Activity_____

Drilling Pits: Closed___ Open___ Wellhead Installed: ____ Sign: Yes___ No___

Tank ID: Yes___ No___ N/A___ Skim Tank/Pit: _____ Prod. Tanks: ( ) _____BBLS

Equipment_____ Meter Run: Yes_____ No_____

Bradenhead Press:_____ Fluid: No____ Yes____ Type_____ Well Cat. ____

AL/PA/DA Inspection

Date Plugged: 1-30-88 Date Permit Expired:_____

Hole Plugged: Yes ↘ No____ Pits Backfilled: Yes ↘ No____

Material Buried: Yes____ No ↘ N/A____ Site Clean: Yes____ No ↘

Bond Release OK: Yes____ No ↘ Fed____ Hole Marker: Yes____ No____

Date of Safety/Status Inspection_____

Comments: TRTR & JUNK, PARTS OF A BLDG.

Violations: Yes_____ No_____ Notice Sent: Yes____ No____ Date Sent:_____