

Inspection Photos
Location Name: FHA 22-1
API Number: 125-07230



1. View of wellhead. Note both the casing valve and bradenhead valve are missing plugs.



2. Bradenhead valve found open at time of inspection.

Inspection Photos
Location Name: FHA 22-1
API Number: 125-07230



3. Well location overview.



4. Lease sign at gathering location.

Inspection Photos
Location Name: FHA 22-1
API Number: 125-07230



5. View of horizontal separator at remote gathering location.



6. Damage to Meter Shed roof.

Inspection Photos
Location Name: FHA 22-1
API Number: 125-07230



7. Gas Meter inside Meter Shed.



8. Gathering location overview.