

Inspection Photos
Location Name: FHA 22-3
API Number: 125-07266



1. Lease sign at well location.

2. View of wellhead. Note no Bradenhead visible at surface.

Inspection Photos
Location Name: FHA 22-3
API Number: 125-07266



3. View of wellhead. Note no Bradenhead visible at surface.



4. Well location overview.

Inspection Photos
Location Name: FHA 22-3
API Number: 125-07266



5. Lease sign at gathering location.



6. View of horizontal separator at gathering location.

Inspection Photos
Location Name: FHA 22-3
API Number: 125-07266



7. View of damaged gas meter Shed roof.



8. Gas meter inside meter shed.

Inspection Photos
Location Name: FHA 22-3
API Number: 125-07266



9. Backside of gathering location overview.



10. Gathering location overview.