

WELL NAME: HILL RANCH 12-04, API #: 071-09849, INSP. # 716301782



PHOTO 1: EMERGENCY CONTACT # IS FAIDED AND NOT LEGIBLE AND NO API # POSTED. POST SIGN IN ACCORDANCE WITH RULE 605. CA DATE 1-8-2026.



Network: Dec 8, 2025 at 9:53:15 AM MST  
Local: Dec 8, 2025 at 9:53:15 AM MST  
+37.016656, -104.954245  
Las Animas County

**PHOTO 2: LOCATION.**



Network: Dec 8, 2025 at 9:57:02 AM MST  
Local: Dec 8, 2025 at 9:57:02 AM MST  
+37.016880, -104.953028  
Los Animas County

**PHOTO 3: WELLHEAD AND EQUIPMENT.**



Network: Dec 8, 2025 at 10:15:54 AM MST  
Local: Dec 8, 2025 at 10:15:54 AM MST  
+37.016954, -104.953254  
Los Animas County

**PHOTO 4: UNUSED EQUIPMENT (2" POLY PIPE ON 15 BBL TANK). REMOVE UNUSED EQUIPMENT PER RULE 606. CA DATE 12-15-2025.**



Network: Dec 8, 2025 at 10:17:34 AM MST  
Local: Dec 8, 2025 at 10:17:34 AM MST  
+37.017096, -104.953443  
Los Animas County

**PHOTO 5: Netting on open top tanks inadequate. Install or repair wildlife protection equipment per rule 608.a.(13). CA DATE 12-15-2025.**



**PHOTO 6: OILY FILM IN COMPRESSOR SKID. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 12-9-2025.**