

Inspection Photos

September 11th, 2025

Operator: Noble Energy Inc.

Location ID: 329750

Inspection Document #: 714002591

County: Weld

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ogg 21-28
Location ID: 329750



Photo 1. Aerial imagery of the Well Pad (highlighted in Red), Access Road (Highlighted in Yellow) and Tank Battery (Highlighted in Blue).

Inspection Photos
Location Name: Ogg 21-28
Location ID: 329750



Photo 2. Aerial view of the well pad and access road taken with a drone during the time of the inspection from the southern edge facing north. Note: Bare ground and crop establishment issues observed at the well pad.

September 11, 2025
71° E



Photo 3. Ground view of the western edge facing center. Note: area vegetation is composed of a mix of perennial grasses.