

WELL NAME: HILL RANCH 35-14, API #: 071-08252, INSP. # 716301788




PHOTO 1: WELL SIGN



**PHOTO 2: LOCATION.**



**PHOTO 3: WELLHEAD AND EQUIPMENT.**



**PHOTO 4: AREA OF IMPACTED SOIL NEAR COMPRESSOR SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 12-15-2025.**



**PHOTO 5: AREA OF IMPACTED SOIL NEAR COMPRESSOR SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 12-15-2025.**



Network:Dec 8, 2025 at 11:56:28 AM MST  
Local:Dec 8, 2025 at 11:56:28 AM MST  
+37.036630,-104.965131  
Los Animas County

**PHOTO 6: OILY WASTE IN COMPRESSOR SKID. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 12-9-2025.**