

Inspection Photos  
Location Name: UPRR 43 Pan Am H 9  
Location ID: 318857




Photo 1 Dead vegetation along access rd.

Photo 2 Dead vegetation around the wellsite.

Inspection Photos  
Location Name: UPRR 43 Pan Am H 9  
Location ID: 318857




Photo 3 Wellhead is SI.

Photo 4 Wellsite sign updated since previous inspection.

Inspection Photos  
Location Name: UPRR 43 Pan Am H 9  
Location ID: 318857



Photo 5 Tall dead vegetation along access rd. around location & equipment.

Photo 6 Tall dead vegetation around location.