

Final Reclamation Inspection

November 13, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 310735

Inspection Document #: 718801090

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HONEBEIN #13-7U
Location ID: 310735



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place. The location has been mowed prior to this inspection, so vegetation establishment will be determined in an inspection at a later date.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: HONEBEIN #13-7U
Location ID: 310735



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos
Location Name: HONEBEIN #13-7U
Location ID: 310735



Photo 5. Photo taken of the access road to the well location, facing south, towards the location. Photo illustrates that final reclamation activities have taken place and vegetation is establishing.



Photo 6. Photo taken of the reference area to the location, east of the location, facing east. Photo illustrates perennial grass vegetation.

