

Final Reclamation Inspection

November 13, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 330632

Inspection Document #: 718801094

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: LATHAM #7-2
Location ID: 330632



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards. Bare ground and weedy annual vegetation, including kochia (*Bassia scoparia*), were observed across the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos
Location Name: LATHAM #7-2
Location ID: 330632



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos
Location Name: LATHAM #7-2
Location ID: 330632



Photo 5. Photo taken of the access road to the well location, facing south, towards the location. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards.



Photo 6. Photo taken of the reference area to the location, east of the location, facing east. Photo illustrates perennial grass vegetation.